**BATCH ID** 2406981.00 i, Inc. A 98103 <del>)6.344:</del>1878

## CHAIN of CUSTODY . NEW ATTPIRESS SAMPLE LOG

5 (685.5227) PAUL W SACKSON & ASSACIATER Client NVL Field Services 36 as BEACH DRIVE NVL Batch Number Street 4708 Aurora Ave. N Client Job Number 2004 **Total Samples** Seattle, WA-98103 98/16 Turn Around Time 🔲 1-Hr □ 24-Hrs □ 4 Days Project Manager P. Jachson 4-Hrs 3 Days 6 to 10 Days
Please call for TAT less than 24 Hrs **Project Location Email address** Phone: (206) 547-0100 Fax: (206) 634-1936 ☐ Asbestos Air ☐ PCM (NIOSH 7400) ☐ TEM (NIOSH 7402) ☐ TEM (AHERA) ☐ TEM (EPA Level II) ☐ Other ☐ Asbestos Bulk ☐ PLM (EPA/600/R-93/116) ☐ PLM (EPA Point Count) ☐ PLM (EPA Gravimetry) ☐ TEM Bulk Other Metals **METALS** Det. Limit **Matrix RCRA Metals** □ All 8 ☐ All 3 Lead (Pb)
Mercury (Hg) ☐ Total Metals ☐ Air Filter ☐ Paint Chips Arsenic (As) ppm (AAS) ☐ Copper (Cu) ☐ Drinking water ☐ Paint Chips (Area) Barium (Ba) TCLP ppb (GFAA) ☐ Nickel (Ni) ☐ Dust/wipe ☐ Waste Water Cadmium (Cd) Selenium (Chromium (Cr) Silver (Ag) ☐ Selenium (Se) ☐ Zinc (Zn) □ Soil ☐ Other Types ☐ Fiberglass ☐ Nuisance Dust ☐ Other (Specify) of Analysis Silica ☐ Respirable Dust Condition of Package: Good □ Damaged (no spillage) □ Severe damage (spillage) Seq.# Client Sample Number Comments A/R 1 RP-519 PI 2 4V-519 P/ 3 519A1 4 519A2 5 519 QA 6 7 8 9 10 11 12 13 14 15 Print Below Sign Below Date Time Company Sampled by Relinquished by Received by 11:25 Analyzed by Cheston Perry Results Called by Results Faxed by Special Instructions: Unless requested in writing, all samples will be disposed of two (2) weeks after analysis.